

# SOLDERING



At start, and every few connections: clean tip of iron on damp sponge, apply thin layer of solder

